

100% PLANT-BASED TART WAX GOLDEN WAX® 494

GENERAL USE GUIDELINES

- ◆ MELTING TEMPERATURE: 175°F (+/-5°F)
- ◆ POUR TEMPERATURE: 160°F (+/-5°F)
- ◆ FRAGRANCE LOAD: 5-10%
- ◆ COOLING: ambient temperature (70-75°F)
- ◆ WAX MELTING POINT: 125-135°F

BENEFITS

may be used alone—no need for paraffin or other non plant-based waxes

creates a fragrance throw comparable to paraffin

reduces set-up time

offers significant bloom/frost reduction

has great mold release

allows for vibrant colors



Conditions will vary based on mold/container type and size, fragrance and dye used