

# 100% SOY CONTAINER WAX GOLDEN WAX® 464

## GENERAL USE GUIDELINES

- ◆ MELTING TEMPERATURE: 175°F (+/-5°F)
- ◆ POUR TEMPERATURE: 135°F (+/-10°F)
- ◆ FRAGRANCE LOAD: 5-10%
- ◆ COOLING: ambient temperature (70-75°F)
- ◆ WAX MELTING POINT: 113-119°F

## BENEFITS

may be used alone—no need for paraffin  
or other non plant-based waxes

offers bloom/frost reduction

single pour



*Conditions will vary based on mold/container type and size, fragrance and dye used*